

ADDENDUM No. 2

Tender: Cape Forchu Lookoff Platform – MODY

Dated: August 25, 2022

Here are the responses to the questions received today from a prospective bidder:

1. In Section 13.1 it states, the owner may require periodic third party inspection however it does not mention who will be responsible for payment of these inspections. Who is responsible for this along with concrete testing if required.

Answer- Third party inspections are the responsibility of the contractor to pay, along with any material testing such as concrete testing.

2. In Section 00300 page 11, it states all site personnel are to have Working from heights training. If the trades work does not include any work from heights, is this required?

Answer- Height training requirement is for those working on the rooftop platform or actually working from heights.

3. What is the desired finish elevation of the ground level viewing platform?

Answer- Finished elevation of the ground platform can be calculated from the approximate values shown on Sheet 5 of the drawings. See the snip below.

